# Limited Mold Assessment Lakeview MS Library

Treadway, David <treadwayd@lisd.net>

Tue 1/18/2022 8:29 AM

To: Deister, Beri <deisterbl@lisd.net>; Samples, Sharla <sampless@lisd.net>; Jones, Victor <jonesv@lisd.net>; Powell, Patricia <powellp@lisd.net>

Cc: Hughes, Jason <hughesjk@lisd.net>; Jones, Steven <jonessa@lisd.net>; Cashman, Jinger <cashmans@lisd.net> Dr. Deister,

Good morning. I am sending this email to follow up with the results of the limited mold assessment that was requested for the Library. The assessment was conducted on December 22, 2021, by Ensolum LLC. It is typically assumed that the indoor spore levels in an area with filtered or air-conditioned air, and activity levels associated with schools, average below the outdoor levels. Data from the airborne mold/fungi sampling indicated that the total indoor concentration of mold/fungi in the library was 8.9% of the outdoor levels. Utilizing this theory, the indoor concentrations were well within the acceptable guidelines for areas with filtered or air-conditioned air at the time of the assessment. The full report will be available on the LISD website. If you have any questions or any other environmental concerns, please feel free to contact me.

Sincerely, David Treadway

David Treadway LISD Environmental Coordinator Facility Services Department



December 28, 2021

Lewisville Independent School District 340 Lake Haven Lewisville, Texas 75057 Attn: David Treadway

Re: Limited Mold Assessment

Lakeview Middle School Library

4300 Keys Drive

The Colony, Texas 75056

Ensolum Project No. 01A1288155

Ensolum, LLC (Ensolum) was retained to perform limited mold assessment services within the Lakeview Middle School Library located at 4300 Keys Drive in The Colony, Texas. Enclosed is the report, including analytical data.

Ensolum appreciates this opportunity to be of service and looks forward to our continued work together. Please contact the undersigned with any questions or concerns you may have.

Sincerely,

Darren G. Bowden

Principal

MAC0321 EXP: 2/15/2022

#### 1.0 INTRODUCTION

Ensolum was retained by David Treadway, LISD, to complete a Limited Mold Assessment within the Lakeview Middle School Library located at 4300 Keys Drive in The Colony, Texas. The purpose of this investigation was to determine if elevated concentrations of airborne fungal spores and structures were present within the above-referenced areas. Ensolum completed the on-site investigation on December 22, 2021. The Limited Mold Assessment was performed in response to a complaint of possible indoor air quality issues within specific areas.

#### 2.0 PROCEDURE

Ensolum visually inspected accessible areas of the Technology Information/Skyward Area. No water damage or odors were observed in the following locations:

LOCATION	DATE	EXPLANATION
		VISIBLE WATER DAMAGE

Following the inspection of potential water-damaged building materials, Ensolum conducted a moisture investigation in the identified areas to determine if nonvisible water-damaged materials and other building materials within the investigation area were present. The moisture investigation was completed with a GE Protimeter BLD5364 moisture meter on accessible porous and semi-porous building materials in each area of concern. At the time of investigation, monitored building materials did not exhibit elevated moisture concentrations in comparison with similar and non-affected building materials in the structure and standard scientific guidelines.

Representative Relative Humidity readings were collected and recorded using an Extech Instruments Humidity / Temperature Pen. Measurements recorded during the investigation are listed in the chart below:

TEMPERATURE,	RELATIVE HU	MIDITY & SPEC	IFIC HUMIDITY	
LOCATION	DATE	Temperature: F	Relative Humidity	Specific Humidity
Library	12-22-2021	57.7	55.5	39.26
Outdoor 1	12-22-2021	65.1	52.6	46.20
Outdoor 2	12-22-2021	67.0	44.9	44.38

Area air samples were collected with Allergenco-D spore trap cassettes and analyzed for airborne fungal spores and structures. Samples were collected at a rate of 15 liters per minute. Indoor air sample(s) were collected for a five (5) minute period (75 liters) at a height of approximately five (5) feet above finished floor (AFF). Outdoor air samples were collected for a five (5) minutes period (75 liters) at a height of approximately five (5) feet above level ground. American Conference of Governmental Industrial Hygienists (ACGIH) guidelines were followed for the sample collection. Fungal air samples were collected in the following areas:

SPORE TR	AP LOCATIONS
SAMPLE NUMBER	LOCATION
30989	Library
341003	Outdoor 1
330997	Outdoor 2

#### 3.0 RESULTS

Currently, there are no regulatory standards for airborne fungal contamination. Therefore, results of the fungal analysis are compared against scientific guidelines. Bioaerosol samples are evaluated by comparing the indoor samples against the outdoor sample. The same types of fungi should be found in both the indoor and outdoor samples.

Should higher fungal concentrations occur in the indoor sample(s) or complaint areas, this generally indicates there is a source of fungal growth in the area. The types of fungi are also evaluated-the same types/genus of fungi should be present in both the indoor/complaint and outdoor/non-complaint samples.

The results of the fungal air samples collected were evaluated. Air testing performed using spore traps found that airborne mold spores within the Technology Information/Skyward Area were considerably lower and were qualitatively like those measured outside of the building at the time the sampling was performed.

#### **CONCLUSIONS**

Based on ENSOLUM's limited assessment and the analytical results, it appears that the indoor air quality, as it relates to airborne fungi, was within recommended guidelines on the day of the assessment.

# APPENDIX A ANALYTICAL DATA



**Summary** 

TDLR License No.: LAB0117 AIHA EMPAT ID: 102577

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

Client: Project: Ensolum, LLC

Lakeview Middle School Library

Project #:

01A 1288155

Sample Type: Spore Trap, Non-cultured

Test Method: Mold: MLQ - 0112 - Standard Profile

Lab Job No.: 21F-15878

Report Date: 12/27/2021

Sample Date: 12/22/2021

Spore Trap Type: Allergenco D

Page 1 of 2

On 12/22/2021, three (3) samples were submitted by Colton Turner of Ensolum, LLC (located at 2351 W. Northwest Hwy Suite #1203, Dallas, TX 75220) for Spore Trap, Non-cultured mold analysis. This report consists of three sections; a summary section, a data detail section, and an analytical notes section.

Sample Number Volume (liters)		Sample Description	Identification	Concentration spores/cubic meter	
30989	75	Library	Basidiospores	200	38%
			Aspergillus / Penicillium	147	28%
			Cladosporium	93	18%
			Hyphal / Spore Fragments - Dematiaceous	40	8%
			Ascospores	27	5%
			Myxomycete / Periconia / Rust / Smut	13	2%
			Total:	520	100%
341003 75	75	Outdoor 1	Basidiospores	1413	44%
			Cladosporium	1026	32%
			Aspergillus / Penicillium	267	8%
		Ascospores	227	7%	
		Hyphal / Spore Fragments - Dematiaceous	107	3%	
		Myxomycete / Periconia / Rust / Smut	67	2%	
			Nigrospora	67	2%
			Cercospora / Pseudocercospora	13	<1%
			Coprinus group	13	<1%
			Torula	13	<1%
			Alternaria	13	<1%
		Total:	3226	100%	



**Summary** 

TDLR License No.: LAB0117 AIHA EMPAT ID: 102577

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

Client:

Ensolum, LLC

Project:

Lakeview Middle School Library

Project #:

01A 1288155

Sample Type: Spore Trap, Non-cultured

Test Method: Mold: MLQ - 0112 - Standard Profile

Lab Job No.: 21F-15878

Report Date: 12/27/2021

Sample Date: 12/22/2021

Spore Trap Type: Allergenco D

Page 2 of 2

On 12/22/2021, three (3) samples were submitted by Colton Turner of Ensolum, LLC (located at 2351 W. Northwest Hwy Suite #1203, Dallas, TX 75220) for Spore Trap, Non-cultured mold analysis. This report consists of three sections; a summary section, a data detail section, and an analytical notes section.

Sample Number Volume (liters)			Identification	Concentration spores/cubic meter	
330997 75	Basidiospores		2914	70%	
	* See Analytical Notes report for further details	Cladosporium	493	12%	
		Ascospores	387	9%	
		Aspergillus / Penicillium	200	5%	
		Hyphal / Spore Fragments - Dematiaceous	67	2%	
		Myxomycete / Periconia / Rust / Smut	27	<1%	
			Nigrospora	27	<1%
			Coprinus group	27	<1%
	Alternaria	13	<1%		
			Total:	4155	100%

This report shall not be reproduced except in full, without approval of the laboratory. Data contained in this test report relates only to the samples tested. This report does not express or imply interpretation of the results contained herein. Interpretation should be made by a qualified professional. Moody Labs assumes no responsibility for the manner in which these samples were collected or handled prior to being received at this laboratory. Volume, area, and/or weight is provided by the customer. Moody Labs assumes no responsibility for the qualifications of personnel performing sampling and/or interpretations of this data.

Analyst(s):

Anshu Singh

Lab Director: Heather Lopez

Lab Director: Bruce Crabb

Thank you for choosing Moody Labs

Approved Signatory:
Approved Signatory:
Bene Vall

SMLMS v13.62



**Data Detail** 

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

Client: Ensolum, LLC

Project: Lakeview Middle School Library

Project #: 01A 1288155

Sample Type: Spore Trap, Non-cultured

Test Method: Mold: MLQ - 0112 - Standard Profile

Lab Job No.: 21F-15878

Report Date: 12/27/2021 Sample Date: 12/22/2021

Spore Trap Type: Allergenco D

TDLR License No.: LAB0117

AIHA EMPAT ID: 102577

This report consists of three sections; a summary section, a data detail section, and an analytical notes section. Results may not be reported except in full. Sample ID: 30989 341003 330997 Location: Library Outdoor 1 Outdoor 2 Media Expires On: Sep 2022 Sep 2022 Sep 2022 Notes Included: See Analytical Notes Volume: 75 75 75 RL spores/m³ %total spores/m³ SF raw ct RL spores/m³ %total spores/m³ SF raw ct RL spores/m³ %total spores/m³ SF raw ct Alternaria 13 13 <1% 10 13 13 <1% 10 27 2 13 5% 30 17 13 227 7% 230 13 387 9% 390 Ascospores Aspergillus / Penicillium 11 13 147 28% 150 20 13 267 270 15 13 200 5% 200 8% 106 1413 1400 2914 2900 Basidiospores 15 13 200 38% 200 13 44% 102 29 70% Cercospora / Pseudocercospora 1 13 13 10 <1% Chaetomium Cladosporium 1000 490 7 13 93 90 1026 32% 493 18% 77 13 37 13 12% Coprinus group 1 13 13 <1% 10 13 27 <1% 30 Hyphal / Spore Fragments - Dematia 3 13 40 8% 40 8 13 107 100 5 13 67 70 3% 2% Hyphal / Spore Fragments - Hyaline Myxomycete / Periconia / Rust / Sm 13 13 10 67 27 30 1 2% 5 13 2% 70 2 13 <1% 67 70 Nigrospora 5 13 2% 2 13 27 <1% 30 Stachybotrys Torula 13 13 10 1 <1% 520 100% 520 3226 100% 3200 4155 100% 4200 **TOTALS** 39 242 195 Analyst Anshu Singh Anshu Singh Anshu Singh Analysis Date 12/27/2021 12/27/2021 12/27/2021 **Debris Rating** 2 2 2 **Debris Composition** 1/5 **Fibers** 1/5 1/5 Inorganic/Other 2/5 2/5 2/5 Insect Parts 0/5 0/5 0/5 Pollen 1/5 1/5 0/5 Skin/Dander 1/5 1/5 1/5

End of Data Detail section 21F-15878

SMLMS v13.62



#### **Analytical Notes**

TDLR License No.: LAB0117

Lab Job No.: 21F-15878

Report Date: 12/27/2021

Sample Date: 12/22/2021

Spore Trap Type: Allergenco D

AIHA EMPAT ID: 102577

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

Client: Ensolum, LLC

Project: Lakeview Middle School Library

Project #: 01A 1288155

Sample Type: Spore Trap, Non-cultured

Test Method: Mold: MLQ - 0112 - Standard Profile

Page 1 of 2

This report consists of three sections; a summary section, a data detail section, and an analytical notes section. Results may not be reported except in full.

#### Samples Analyzed

Sample No:

330997: Outdoor 2

Notes:

Please note: the minimum reporting limit for Basidiospores is 29 spores / cubic meter. When comparing

results to other samples, use calculated results, not raw numbers.

#### Field Blanks

No discernable field blanks were submitted with this set of samples.

NOTE: All remaining samples suitable for analysis.

#### Methods

Method: MLQ - 0112 / ASTM D7391: Categorization and Quantification of Airborne Fungal Structures in an Inertial Impaction.

Sample by Optical Microscopy.

Samples are read at 100% under 400x magnification unless noted. Partial readings may be employed when concentrations are elevated. Use final spore concentrations, not raw spore counts, for interpretation of results.

Calculation: Spores/cubic meter = (Raw spore count)\*(RL)

Note: RL (Reporting Limit) is based upon 1 raw spore count.

Moody Labs recommends two significant figures for calculated values based on ASTM D7391.

This report must not be used by the customer to claim product certification, approval, or endorsement by AIHA, ISO, or any agency of the Federal Government.

#### **Debris Rating Key**

- 0 No linear trace detected
- 1 Trace particulate/debris
- 2 Light particulate/debris
- 3 Moderate particulate/debris
- 4 Substantial particulate/debris
- 5 Extensive particulate/debris
- 6 Field blank
- 10 Hold Sample
- 11 Modified Analysis per Client Instructions

NOTE: Particulate/debris are defined as skin, fibers, pollen grains, insect parts, fungal and/or other non-fungal particles.



**Analytical Notes** 

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

Client: Ensolum, LLC

Project: Lakeview Middle School Library

**Project #:** 01A 1288155

Sample Type: Spore Trap, Non-cultured

Test Method: Mold: MLQ - 0112 - Standard Profile

**Lab Job No.:** 21F-15878 **Report Date:** 12/27/2021

Sample Date: 12/22/2021


Spore Trap Type: Allergenco D

Page 2 of 2

TDLR License No.: LAB0117

AIHA EMPAT ID: 102577

This report consists of three sections; a summary section, a data detail section, and an analytical notes section. Results may not be reported except in full.



Lab 10 # 102571












End of Analytical Notes section 21F-15878





TDLR License No.: LAB0117 AIHA EMPAT ID: 102577 12/27/2021 Sample Date: 12/22/2021 21F-15878 Report Date Lab Job No. ☐ Average Reference 2 Average Reference 2 = Outdoor 2 Supplemental Overview IAQ Mold Report Torula Stachybotrys Nigrospora Average Reference 1 Myxomycete / Periconia / Rust / Smut Hyphal / Spore Fragments - Hyaline Hyphal / Spore Fragments - Dematiaceous Coprinus group Cladosporium Chaetomium Farmers Branch, TX 75234 Phone: (972) 241-8460 Lakeview Middle School Library Sample Sample Cercospora / Pseudocercospora Basidiospores Average Reference 1 = Outdoor 1 Ensolum, LLC 01A 1288155 Aspergillus / Penicillium 2051 Valley View Lane Ascospores Alternaria Project #: Project: Client: 200 3500 3000 2500 1000 2000 1500 0

TDLR License No.: LAB0117 AIHA EMPAT ID: 102577 21F-15878 12/27/2021 Sample Date: 12/22/2021 Report Date Lab Job No. Average Reference 2 Average Reference 2 = Outdoor 2Supplemental Overview IAQ Mold Report Torula Stachybotrys Nigrospora Average Reference 1 Myxomycete / Periconia / Rust / Smut Hyphal / Spore Fragments - Hyaline Hyphal / Spore Fragments - Dematiaceous Coprinus group Cladosporium Farmers Branch, TX 75234 Phone: (972) 241-8460 Chaetomium Lakeview Middle School Library Sample Cercospora / Pseudocercospora Basidiospores Average Reference 1 = Outdoor 1 Ensolum, LLC 01A 1288155 Aspergillus / Penicillium 2051 Valley View Lane Ascospores Alternaria Project #: Project: Client: 3500 3000 2500 1000 200 0 2000 1500

TDLR License No.: LAB0117 AIHA EMPAT ID: 102577 12/27/2021 21F-15878 Sample Date: 12/22/2021 Report Date Lab Job No. Average Reference 2 Average Reference 2 = Outdoor 2Supplemental Overview IAQ Mold Report Torula Stachybotrys Nigrospora Average Reference 1 Myxomycete / Periconia / Rust / Smut Hyphal / Spore Fragments - Hyaline Hyphal / Spore Fragments - Dematiaceous Coprinus group Cladosporium Chaetomium Farmers Branch, TX 75234 Phone: (972) 241-8460 Lakeview Middle School Library Sample Cercospora / Pseudocercospora T Basidiospores Average Reference 1 = Outdoor 1 Ensolum, LLC End of Supplemental Overview section 01A 1288155 Aspergillus / Penicillium 2051 Valley View Lane Ascospores Alternaria Project #: Project: Client: 3500 3000 2500 2000 1000 200 0 1500 21F-15878

# **APPENDIX B**

## **DEFINITIONS AND LIMITATIONS**



#### **Mold Services Definitions & Limitations**

Ensolum performed services in accordance with generally accepted practices of the profession undertaken in similar services at the same time and in the same geographical area. No other warranties, express or implied, apply to the services hereunder or the final report.

Ensolum's services and any report have been prepared on behalf of and for the exclusive use of the Client solely for its use and reliance in assessing the presence of mold in the Investigation Areas of the site. The Client was the only party to which Ensolum explained the risks and limitations of the services and was solely involved in shaping the scope of services. Accordingly, reliance on this report by any other party may involve assumptions leading to an unintended interpretation of findings and opinions. With the consent of the Client, Ensolum may offer reliance to third parties or contract with other parties to develop findings and opinions related to such party's unique risk management concerns. Notwithstanding the foregoing, reliance by any and all third parties upon this deliverable, Ensolum's services or any subsequent report shall be limited in the aggregate to the fair market value of the services provided by Ensolum.

"Limited Mold Assessment". This deliverable uses the term "Limited Mold Assessment" to denote that Ensolum's mold assessment services are limited: (i) to certain portions of the building structure (e.g., the Investigation Areas), by non-destructive sampling methodologies, and/or by access limitations to building materials or components within the Investigation Area(s). In contrast to a "Limited Assessment" is a comprehensive assessment would involve destructive sampling methods with the assessment to be conducted throughout the entire building structure.

Time sensitive. One must keep in mind that mold assessments are essentially a "snap shot in time," and the results are only relevant at the time of site reconnaissance. Because mold, when biologically active, is a living organism, its presence is influenced and controlled by environmental conditions. Mold assessments, therefore, are "time sensitive" in that the presence and concentration of mold and similar organisms in building structures or in the air is directly influenced by environmental conditions (such as humidity, moisture, nutrients and substrates), whether natural or caused by man, which conditions may vary significantly over relatively short periods of time.

Methodologies. Currently, mold assessment methodologies and protocols in Texas are governed by persuasive guidelines (rather than promulgated federal/state or local regulations). Presently, there is no data that supports a threshold limit or dose-response relationship for exposure to mold aeroallergens, individual pathogens, opportunistic pathogens and/or mycotoxins. The Occupational Safety and Health Administration (OSHA), the National Institute of Occupational Safety and Health (NIOSH) and other non-governmental associations, have not yet established permissible exposure limits (PELs), recommended exposure limits (RELs), or other limit values for fungi. Because no limit values presently exist. Ensolum will not and cannot represent that the site contains no harmful microbes, mold, fungi, or their metabolites, or other latent conditions beyond those identified by the limited scope of this mold assessment.



Findings limited. Findings in an LMA are limited due to the nature of the information obtained such as a visual reconnaissance of readily accessible areas of building structures, interview information, anecdotal information, and limited sampling data derived from one or more specific sampling events. Ensolum cannot warrant the accuracy of prior or subsequent information/data, reports and services performed by other firms at the Site. Ensolum assumes no responsibility or liability for errors in information or data provided by or through the client or third party sources. Ensolum's services are not to be construed as legal or medical interpretation or advice.

Moisture Intrusion Limitation. Ensolum performs mold assessment services and is not a moisture intrusion, HVAC, plumbing or building envelope specialist. However, during the course of conducting its mold assessment services, Ensolum will report observed areas of apparent moisture intrusion. Ensolum does not and will not investigate the cause or causes of such observed moisture intrusion. In the event apparent moisture intrusion is observed, Ensolum will recommend that the client contact a specialist (i.e., plumbing contractor, building envelope specialist, HVAC contractor, water intrusion specialist, etc.) to assist the client in determining the specific cause or causes of the moisture intrusion and remedial options.

Certificate of Mold Damage Remediation (CMDR). For mold remediation projects (above certain size thresholds), applicable Texas law (i.e., Texas Occupation Code Section 1958.54 and T.A.C. Section 295.397 (the Texas Mold Assessment and Remediation Rules), requires that a "Certificate of Mold Damage Remediation" be issued by the Mold Remediation Contractor upon successful completion of the project. This certificate must be provided to property owners no later than the 10<sup>th</sup> day after the date on which the mold remediation is completed at a property. The Mold Remediation Certificate issued by the Mold Remediation Contractor must include a certification by the Mold Assessor that the mold remediation project has been successfully completed in accordance with the mold remediation protocol.

Be advised that Ensolum's issuance of a CMDR upon successful completion of a Mold Remediation project does not mean, warrant or otherwise guarantee that mold will not be subsequently found in any portion of an Investigation Area or the Site. In the event that Ensolum is engaged to render services in connection with a mold remediation project, ENSOLUM will require Client to provide to Ensolum written documentation that all sources of moisture which contributed to the presence of mold in the Investigation Area have been fully remediated and corrected prior to achieving clearance.